



Access
the
inaccessible®

[CRITICAL AND URGENT]

Request for inspection of Petzl low-stretch kernmantle ropes

© Petzl Distribution / Lafouche

Petzl Crolles, France, July 24, 2020

Dear Customers,

We are issuing [a request for your inspection of the Petzl low-stretch kernmantle ropes](#) identified below with a serial number in the following range:

18 C 0000000 000 < Serial number < 20 H 0000000 000

The affected ropes are:

- AXIS 11 mm
- ASAP'AXIS 11 mm
- PARALLEL 10.5 mm
- VECTOR 12.5 mm
- RAY 12 mm
- SEGMENT 8 mm
- CLUB 200 10 mm
- PUSH 200 9 mm
- TOP 9.8 mm
- LEAD 9.8 mm
- Kits that include these ropes

If you own any of these ropes, we ask that you immediately inspect them in accordance with the [operating procedure document on Petzl.com](#) and register the inspection result in accordance with the [operating procedure document on Petzl.com](#).

The inspection we are asking you to carry out fulfills certain criteria from the detailed periodic inspections you must carry out at least once every 12 months. If you encounter any difficulty carrying out the inspection, please [contact us](#).

We are available to answer any questions you may have, and sincerely apologize for the inconvenience.

Best regards,



www.petzl.com